

# Engineering Product Advisory

Subject: Drawing incorrect  
Product: V1500CDU to V1400X-IDL to V1400X-DVC KEYPAD  
Number: 1400-0035-01-00  
Date: April 10, 2003

**PRODUCT: V1500CDU to V1400X-IDL to V1400X-DVC Keypad Interconnect Drawing (Drawing # 1400-0103-80 Rev 02)**

**PROBLEM: RJ45 Termination Box wired incorrectly**

**SOLUTION: Cmd In- was shown incorrectly to screw #3 of Termination Box. Revised drawing to show it terminated to screw #4**

**NOTES: Also filed as ddn#2151**

